
CITY OF BALTIMORE WET SMOKE AND DYED I	Page 1 of 3			
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 08/26/2008		
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_	Supervisor: E.R. Crew: 04		
Manhole ID: S15G011MH	Test ID: 1029-600	Notifications Made:X Residents, Fire, 311		

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM								Page 2 of 3							
	Sewershe	ershed: Low Level ubsewershed: 44 Company: REI/DRAYCO									Date: 08/26/2008				
Test Type: Smoke					Ground Condition:						Supervisor: E.R. Crew: 04				
rest Type. Officie					Dry: X Damp:_ Wet:_					Notifications Made:X					
Manhole ID: S15G011MH					Test ID: 1029-600						Residents, Fire, 311				
Field S	ketch: (Sho	w all	manholes with nun									ons, s	treet names,	building addr	esses
Defect	· I			ina iod	ations, det Source										
No.	Address				Type		Location	Sector	Drainage Area	_	Severity		Photo	Number	
1					02	06		02	5		03	10		B01-01.jpg	
													_	л о	
	+														
	1														
	 														
	 														
						<u> </u>			ļ						
	1														
					OP.	SED	\/ \ T	ION CO	DEC			<u> </u>			
	Sour	ce T	VDE	1	ОВ				DES		Sector		Sev	verity	
Source Type 01 Main Sewer 10 MH Frame 01			01	Location 01 Paved Conc. 10				Public	Severity 01 No Smoke						
02 Service Line 11 Storm Drain								02	Private		Trace	-			
03 CI	03 Cleanout 12 Catch Basin			3 Paved Other 1								Moderate			
	04 Downspout 13 Storm MH		04			13						Major			
05 Aı	D5 Area Drain 14 Storm Ditch		_	Sidewal	k	14									
	06 Dwy. Drain 15 Excavation			Curb											
	7 Stair. Drain 16 Water Line			Yard - F											
	08 Found. Drai 17 Tele. Pole 09 Bldg. Interio 18 Other			08 Yard - Back							-				
ug IBI	aa. Interio	18	Utner	II U9	raro-S	iae		ĺ		i		I	1		

PAGE 3 of 3

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 600 Date: 08/26/2008 Basin: LL - 44 Manhole ID: S15G__011MH Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 2704 KINSEY AVE.

Source Type: 02 Service Line Sector: 02 Private

Location: 06 Curb Severity: 03 Moderate Drainage Area: 5

Comments: SMOKE IS COMING OUT FROM BELOW CONCRETE SLAB.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-600_OB01-01.jpg